



6026-2415 Natural Wood Drying Rack ©2012 Whitmor, Inc.

This product is intended for drying laundry.



A 5 ea
Long hanging bar




B 1 ea
Medium hanging bar




C 2 ea
Short hanging bars



D 3 ea
Center hanging bars



E 1 ea
Left side frame



F 1 ea
Right side frame



G 16 ea
Locking collar
(Inserted into parts E & F)



H 6 ea
Collar ring




I 6 ea
Screw


Tools Needed:
Phillips Screwdriver,
and Coin or Standard
Screwdriver

STEP 1 Begin with the right side frame (F) and place it on a hard, flat surface like the floor. Make sure all locking collars (G) are inserted correctly as it came from the box. Place 3 collar rings (H) over exposed locking collars on right side frame. Snap five long hanging bars (A), one medium hanging bar (B) and two short hanging bars (C) into locking collars (G) in right side frame. Place the three center hanging bars (D) into center axis of side frame. Secure center hanging bars with three screws (I) using a Phillips screwdriver (not included).

NOTE: Make sure the tabs on end of hanging bars (A, B, & C) line up with notch in locking collar (G).




STEP 2 Next, place 3 remaining collar rings (H) over exposed locking collars on left side frame (E). Place left side frame (E) onto each hanging bar snapping in place just like the right side was done. Secure center hanging bars with three screws (I) using a Phillips screwdriver.




6026-2415 Natural Wood Drying Rack ©2012 Whitmor, Inc.

STEP 3 Your final Whitmor Natural Wood Drying Rack should look like this. Enjoy its use.



Parts Breakdown: Left and right side frames should already be assembled from the box, but this parts breakdown should help if any questions still remain.



NOTE: Top section of side frame (E & F) axis is not centered. Short end of side frame is up.

Part	Reference
A	F6773
B	F6774
C	F6775
D	F6776
E	F6777
F	F6778
G	F6779
H	F6780
I	F6781



8680 Swinnea Road • Suite 103 • Southaven, MS • 38671

NEED HELP? For help with assembly, or if you are missing a part, please call Whitmor's Customer Service Department, 1-888-944-8667 between 8 a.m. and 4:30 p.m. (Central Standard Time) Monday through Friday. Or email: customer_service@whitmor.com. Visit us online at www.whitmor.com